B.R No. 120/2013-14 Dated: 29.06.2013

Inspection report for the Work of: Providing Rain Water harvesting Structires in Ward No. 10 (Doddabommasandra), Vidyarnyapura Sub Division.

By,

Sri G.M. Muniyappa

Inspection Report

Name of Work	:	Providing Rain Water harvesting Structires in Ward No. 10 (Doddabommasandra), Vidyarnyapura Sub Division.
Work Order	:	EE/BTP/BBMP/E-TND/02(143)/WO/227/2012-13 Dated: 29.12.2012.
Agency	:	Narayanaswamy. S
B.R. No & Date	:	120/13-14 Dated: 29.06.2013
Bill Amount	:	3,82,154.91
Job Code	:	010-12-000045
P. Code	:	P-1771
Date of Inspection	:	29-06-13

The above said work providing Rain Water harvesting structures in Ward No 10 has been shown by the Concerned AE.

The above said work has been inspected along with Concerned AE.

The Measurements have been checked by me and it is found satisfactory.

Executive Engineer
Byatarayanapura Division
Yalahanka Zone, B.B.M.P.
Bangalore-560092

29/6/13

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Sketch Showing the Work of Providing Rain Water harvesting Structires in Ward No. 10 (Doddabommasandra), Vidyarnyapura Sub Division.



Jadhav
AE W-10

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

22/06/18

Photos for the Work of Providing Rain Water harvesting Structires in Ward No. 10 (Doddabommasandra), Vidyarnyapura Sub Division.

Jadhav
AE W-10

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Inspection Report

Name of Work	:	Providing Rain Water harvesting Structires in Ward No. 10 (Doddabommasandra), Vidyarnyapura Sub Division.
Work Order	:	EE/BTP/BBMP/E-TND/02(143)/WO/227/2012-13 Dated: 29.12.2012.
Agency	:	Narayanaswamy. S
B.R. No & Date	:	120/13-14 Dated: 29.06.2013
Bill Amount	:	3,82,154.91
Job Code	:	010-12-000045
P. Code	:	P-1771
Date of Inspection	:	



Jadhav
AE W-10

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT